

**2011 to 2015**

**Q80031501 - When we install Windows Server  
2012 R2 on an Areca controller, we have the  
option to remove the controller's volume in the  
OS.**

In new driver codes, volumes listed as eject-able devices due to thunderbolt support.

Unique solution ID: #1063

Author: Simone

Last update: 2022-01-06 07:15