

**2010 to 2015**

**Q60011309 - ARC-5040 with the Esata Cable to Fujitsu Celsius R920 Computer (C600 chip set) instantly gets a BSOD on Windows 7 X64. BSOD always says "iastorA.sys" .**

The Computer which is working with ARC-5040 using an older driver for the c600 chipset. The working driver version is: 3.0.4.1006 and Driver Date is: 09.03.2012

Unique solution ID: #1312

Author: Simone

Last update: 2021-02-04 10:49