

2017

**Q10021412 - There have two ARC-1264IL-16
Controllers, according to the System Info one has
a 800MHz ARM CPU, the other (identical Card)
has a 933MHz ARM CPU?**

You can use the firmware version 1.52 2014-11-11 or later in our website if you would like to use same 933MHz frequency on ARC-12x4 RAID cards.

Unique solution ID: #1166

Author: Simone

Last update: 2015-08-24 09:38