

2015

**Q10261403 - Install an ARC-1882 in a HP Z-820
Work Station and get the following error:
"928-Fatal PCIe error, PCIe error detected Slot X
Reset caused by SERR".**

This issue can be solved by disabling the 'pcie gen 3.0 support' setting in system configuration page.

Unique solution ID: #1099

Author: Simone

Last update: 2015-08-24 09:23