

2014

Q10061304 - Areca 1882i with firmware Version = V1.51 2013-01-23, I set up a passthrough SSD, all settings in web interface are ok but I can't see this passthrough disk on Mac Pro disk utility

It is a bug in this version firmware. Passthrough disks will be hidden by the encryption feature. It has fixed on the new released version.

Unique solution ID: #1257

Author: Simone

Last update: 2015-08-24 09:58