

**2014**

**Q10091307 - The HP Compaq Elite 8300  
MBIOS=K01 v02.05 hangs when attempting to  
access ARC-1214-4I RAID controller BIOS  
configuration via TAB or F6.**

Issue has been resolved by updating M/B BIOS.

Unique solution ID: #1271

Author: Simone

Last update: 2015-08-24 10:33