

**2013**

**Q10031311 - Under MAC PRO machine, update to firmware 1.52 all files , and then reboot it can not boot from the original bootable volume on the RAID controller.**

Please set the BIOS Selection option on the Advanced Configurations to EFI.

Unique solution ID: #1294

Author: Simone

Last update: 2015-08-24 11:17