

2013

**Q10091307 - The HP Compaq Elite 8300
MBIOS=K01 v02.05 hangs when attempting to
access ARC-1214-4I RAID controller BIOS
configuration via TAB or F6.**

Issue has been resolved by updating M/B BIOS.

Unique solution ID: #1271

Author: Simone

Last update: 2015-08-24 10:33