

**2011**

**Q10051101- Are there any known compatibility issues with the ARC-1880 and the Seagate 10k4 600GB SAS drives?**

Please visit our ftp site to download the new firmware 1.49. The older firmware does not support SED drives yet, new version is needed. All Areca controllers do support SED drives but not support SED feature.

Unique solution ID: #1379

Author: Simone

Last update: 2015-08-25 04:02