

2012 to 2013

**Q10061203 - Installing RHEL 6.2 doesn't work
with the ARC-1882i controllers plugged in X8DTH-
IF-B BIOS Version: 2.0c. It start to load of
installer got stuck at "Waiting for hardware
initialization".**

BIOS update to R2.1a solved this issue.

Unique solution ID: #1343

Author: Simone

Last update: 2022-01-06 08:28