

2010

Q10171012 - We have a 10 order of 8TB R5 units (ARC-1201) built up and we appear to be having DHCP IP issues. I have DHCP enabled but the Current IP Address is still the Local IP Address (Static IP). It doesn't appear to be releasing the Static and/or pulling in a DHCP.

The DHCP server did not make big enough range to assign enough IPs.

Unique solution ID: #1479

Author: Simone

Last update: 2015-08-25 04:30