

Q50011609 - Areca 12G expanders do not respond to locate lights from LSI 6G or 12G (or Intel) RAID card, once the drive is part of a RAID.

This issue has been fixed from the expander firmware to revision date: 2016-08-17 or later.

Unique solution ID: #1628

Author: Simone

Last update: 2021-02-04 10:46