

**2020**

**Q80012012 - The driver is working fine until the system tries to install the latest security patch for OS x. During the installation of this patch the system crashes with the log message.**

After the security update has been installed, you need to use the shutdown with installation option instead of reboot and install.

Unique solution ID: #1934

Author: Simone

Last update: 2020-12-02 07:38