

2018

**Q80021704 - By using 6x ST4000NM0115 drives
at ARC-5028T2 if you cause a disk failure
(removing disk or "set disk to be failed") other
drives get also failed.**

This compatibility issue only happens on 1.54_2016_11_23 firmware version. It has been fixed on 1.54_2017_03_27 version.

Unique solution ID: #1675

Author: Simone

Last update: 2017-04-27 09:59