

2015

Q80011506 - The Mac OS X system just needed to be rebooted after installing mraid. Maybe a restart should be added to the installer.

Archttp is a daemon utility that runs a background task. User needs to reboot to take effect. CLI is a foreground utility. You donot need to reboot it after you finish installing. There has one message on the last installation page to request user to reboot the system.

Unique solution ID: #1236

Author: Simone

Last update: 2015-08-24 06:30