

**2015**

**Q10061510 - Samsung SSD 850 PRO 1TB  
Firmware Version = EXM02B6Q drives are  
showing "Time Out Error".**

Disable SATA NCQ support in controller setting fixes this compatible issue.

Unique solution ID: #1509

Author: Simone

Last update: 2015-10-13 11:20