

2016 to 2020

Q60011903 - When ARC-8050U3-6 USB-C raid enclosure plugged into the super micro mother board it is not allowing the M/B to boot.

They had an issue on M/B end and were able to fix with a custom updated the M/B BIOS from super micro.

Unique solution ID: #1839

Author: Simone

Last update: 2021-02-04 10:57