

**2014**

**Q10031410 - Two Bad**

**drives: Hus724040ale640 connected to Areca  
1882X, can't power on server and time out after  
300secs.**

This issue has be fixed into firmware 1.52 date: 2014-09-11 or later.

Unique solution ID: #1213

Author: Simone

Last update: 2015-08-24 06:20