

2011 to 2015

**Q80031501 - When we install Windows Server
2012 R2 on an Areca controller, we have the
option to remove the controller's volume in the
OS.**

In new driver codes, volumes listed as eject-able devices due to
thunderbolt support.

Unique solution ID: #1063

Author: Simone

Last update: 2022-01-06 07:15