

**2013**

**Q80031312 - I Have been getting error messages when I connect my Mac Pro to my ARC-8050. The LED reads Fan #! Failure. The fan appears to be running when I looked at the back.**

User is working on controller temperature 24°C. It is a low temperature environment issue. It can be fixed by firmware version 1.52 date: 2013-12-10 or later.

Unique solution ID: #1329

Author: Simone

Last update: 2015-08-24 08:30