

2020

Q10031901 - If I try to create RAID volumes using Toshiba's HDD * 6, MN05ACA800, it does not start the initialization.

Setting the "Write Same for Initialization" to disabled rather than the default of SAS/SATA Write Same has resolved the initialization issue. You can find 'Write Same for Initialization' feature in web manager console, System Control > System Configuration menu.

Unique solution ID: #1799

Author: Simone

Last update: 2019-01-28 04:15